Plant Cleaning



FEATURES

EASY SITE ESTABLISHMENT (1-HOUR)

Requirements:

- 210 L/min water @ 2-bar
- 525 ACV welding plug connection
- 2 sq/m waterjet space allocate

Cleaning of:

- Shafts & Ore Passes
- Conveyor belt spillage
- Dams & Sumps
- Silos & Tanks
- Thickeners
- Tailing Dams
- Service Steel Structures up to 6 meters

